

## **Under Review Notification**

Raised By: Ketan Tailor

Date: 29/11/2018

**Product #:** Dart Tooling Bell

## **Product Name:** Install Sleeve T/R Gearbox Output Shaft

**Description of Issue:**

For item -1: Incorrect thread size. 1-1/8"-12 thread should be 1-3/16"-18

For item -9: Material change from phenolic to delrin

All stock must be quarantined

## Distribution:

VP Operations

## Director of Operations

Director Quality Assurance

## QC Coordinator

Director of Engineering

## Chief Engineer

## Engineering Project Managers

## Engineering Clerk

## Customer Support Manager

## Production Engineers

## Production Planners

## Purchasing Manager

Technical Support

Product Manager - Solutions Provider

## Supply Chain Director / Senior Buyer

Marketing Eugene